



Technical Data

Color	Royal
Sizes Available	XS-5XL
Packaging	Case
Packed	1/Case
Case Dimensions (in)	24.02 x 15.98 x 12.01
Case Weight (lbs)	2.01
Country of Origin	Mexico
Clothing Type	Lab Coats
Closure	Snap
Construction	ESD Safe
Certifications	TAA Compliant
Product Circularity	Reusable / Launderable

Uniform Technology™

StatStar Short ESD Labcoat

- StatStar Fabric - 87% Polyester / 13% Carbon
- Lapel collar
- Three patch pockets
- Snaps at front opening
- Grounding snap on waist pocket
- Snap wrist closure
- Pen slot on breast pocket
- ESD safe compliance to ANSI/ESD S20.20-2014 - Groundable Static Control Garment

Performance Data

ISO Cleanroom	--
ANSI/ESD S20.20	Groundable Static Control Garment < 1x10 ⁹ Ω Point to groundable point
Temperature Resistant	--
Static Control Property	Static Dissipative

Care Instructions

Our garments do not come wearer ready meaning they need to be laundered before an employee wears them in an ISO class cleanroom. Average wear and tear lifespan is 50-100 washes. Make sure all zippers and snaps are closed. Use less harsh soap (milk alkaline or neutral soaps) or detergents. Wash at 120°F for colors and 140°F for whites. Rinse cold. No bleach. Tumble dry moderate (140°F). After drying tumble dry cold for 5 minutes. No iron.



SPECIFICATION SHEET

STYLE: BR49A-44WH



Technical Data

Color	White
Sizes Available	XS-5XL
Packaging	Case
Packed	1/Case
Case Dimensions (in)	24.02 x 15.98 x 12.01
Case Weight (lbs)	2.01
Country of Origin	Mexico
Clothing Type	Lab Coats
Closure	Snap
Construction	ESD Safe
Certifications	TAA Compliant
Product Circularity	Reusable / Launderable

Uniform Technology™

StatStar Short ESD Labcoat

- StatStar Fabric - 87% Polyester / 13% Carbon
- Lapel collar
- Three patch pockets
- Snaps at front opening
- Grounding snap on waist pocket
- Snap wrist closure
- Pass-throughs slits at waist for pocket access
- ESD safe compliance to ANSI/ESD S20.20-2014 - Groundable Static Control Garment

Performance Data

ISO Cleanroom	--
ANSI/ESD S20.20	Groundable Static Control Garment < 1x10 ⁹ Ω Point to groundable point
Temperature Resistant	--
Static Control Property	Static Dissipative

Care Instructions

Our garments do not come wearer ready meaning they need to be laundered before an employee wears them in an ISO class cleanroom. Average wear and tear lifespan is 50-100 washes. Make sure all zippers and snaps are closed. Use less harsh soap (milk alkaline or neutral soaps) or detergents. Wash at 120°F for colors and 140°F for whites. Rinse cold. No bleach. Tumble dry moderate (140°F). After drying tumble dry cold for 5 minutes. No iron.

KEY: Made from recycled or bio-based Launderable Recyclable via TerraCycle®