





## **Industrial Seating Conductive Fabric Chairs**

**Upholstry Colors and Options** 



### **Conductive Fabric Options:**



Charcoal







**Seat Back Options:** 



High Back



Medium

#### **Armrest Options:**



Fixed Height and Width Arms



Fixed Height and Adjustable Width Arms



Adjustable Height and Width Arms

#### **Adjustment Options:**



Height and Back Tilt. This control has two levers for seat height and back angle adjustment and back height adjustment with knob.



Height and Seat and Back Tilt. This control has two levers, one for height adjustment and the other for Seat and Back tilt adjustment and back height with knob.



Three Lever for Individual Lift. Height lever adjustment, seat tilt adjustment back tilt adjustment and height back adjustment with knob and a seat tension knob.

## **Footring Options:**



**Knobless Nylon Footring 18**". The Footring is Loosened and Tightened by Turning the Outer Ring.



Knobless Aluminum with Steel Ring 20". The Footring is Loosened and Tightened by Turning the Outer Ring.



Nylon Center with Steel Ring, Footring 18"

#### **Caster Options:**



**ESD Braking Caster**, Recommended where Chairs may roll to easily when is Not Occupied.



**ESD Soft Urethane Braking Caster**, Recommended for reduce Mobility when is Not Occupied.



**ESD Soft Urethane Caster**, Recommended on Tile, Cement and other Hard Surfaces.



**ESD Nylon Glide**, Recommended for use in areas where requiring limited mobility.

PAC Midwest Eden Prairie, MN (888) 903-0333 PAC South Central Dallas, TX (800) 442-4008 PAC West Los Angles, CA (888) 839-3936 PAC Mexico Tecate, Mexico (619) 573-4501



# **Industrial Seating Conductive Fabric Chairs**

**Upholstry Colors and Options** 

## **Base Options:**



Polished Aluminum Base



Black Nylon Base